

Lead-Based Paint Survey Report

For

**City of Colorado Springs
Housing Development Division
30 S Nevada Ave, Suite 604
Colorado Springs, CO 80903**

**Linda Clemons
22 W Mill Street
Colorado Springs, CO 80903**

719-385-0468

**For the Dwelling Located at:
22 W Mill Street
Colorado Springs, CO 80903**

Performed By

**John C. Burnside
Certified Lead-Based Paint Inspector/Risk Assessor
Colorado Certification 11876**

**Burnside Enterprises, LLC
4030 Zurich Drive
Colorado Springs, CO 80920
(719)-596-4656**

Colorado Firm License LEF #11738

July 21, 2016

Survey Background Information

Burnside Enterprises, LLC has completed a limited lead-based paint survey at 22 W Mill Street, Colorado Springs, CO 80903, which was performed on July 21, 2016. The dwelling interior consists of plaster with the exterior consisting of vinyl siding with vinyl trim. Wood windows were present throughout the house. The structure is approximately 884 square feet and built in 1895. The area surveyed for lead-based paint included the bathroom area and the interior and exterior window surfaces. No other areas were surveyed.

The standard for lead-based paint, as per HUD/EPA and the State of Colorado standard for XRF measurement of $\geq 1.0 \text{ mg/cm}^2$ as being classified as positive for lead-based paint was followed. All requirements for the NITON XRF contained in the Performance Characteristics Sheet for the NITON XLp-300 were followed.

The painted surfaces in the rooms are identified as components, which can generally be defined as architectural features of the building. Components consist of walls, ceilings, floors, doors, door jambs, window sashes, window sills, stair treads, etc. These are the visible parts of the building. Painted and/or stained components are tested. Each component may be represented many times in a single room. For example, there are generally baseboards on all walls in a room. It is not necessary to test each of these baseboards in the room as long as they appear to have the same paint history. Components covered with vinyl and/or metal siding are not inspected (as these surfaces below these components are not visible or accessible for this survey. This does leave the possibility that lead-based painted components could be located beneath these coverings). The A side would refer to the address side wall of the dwelling with the B, C, and D designations referring to the remaining walls and/or components in a clockwise rotation.

Testing was performed using a NITON XLp-300 X-Ray Fluorescence Spectrometer (XRF), serial number 94979.

Executive Summary

A limited survey for lead-based paint was performed at 22 W Mill Street, Colorado Springs, CO 80903, on July 21, 2016 by John Burnside of Burnside Enterprises, LLC (Colorado Certification 11738), 4030 Zurich Drive, Colorado Springs, CO 80920. Testing was performed using a NITON XLp-300 X-Ray Fluorescence Spectrometer (XRF), serial number 94979. The survey indicated that based upon the current HUD guideline levels, **the following components in the surveyed area were found to contain lead-based paint above or equal to 1.0 mg/cm²:**

| No | Room | Side | Structure | Feature | Substrate | Color | Condition | Results | PbC | Units |
|----|----------|------|-----------|---------|-----------|-----------|-----------|----------|------|--------|
| 5 | Exterior | A | Window | Frame | Wood | Green | Poor | Positive | 5.4 | mg/cm2 |
| 8 | Exterior | B | Window | Frame | Wood | Green | Poor | Positive | 5.2 | mg/cm2 |
| 4 | Exterior | A | Window | Sash | Wood | Green | Poor | Positive | 1.8 | mg/cm2 |
| 16 | Exterior | D | Window | Sash | Wood | Green | Poor | Positive | 1.4 | mg/cm2 |
| 18 | Rm. 01 | A | Window | Casing | Wood | Brown | Intact | Positive | 11.7 | mg/cm2 |
| 19 | Rm. 01 | A | Window | Sash | Wood | Brown | Intact | Positive | 9.3 | mg/cm2 |
| 20 | Rm. 02 | A | Window | Casing | Wood | Off-White | Intact | Positive | 7 | mg/cm2 |
| 21 | Rm. 02 | A | Window | Sash | Wood | Off-White | Intact | Positive | 5.4 | mg/cm2 |
| 24 | Rm. 03 | A | Window | Casing | Wood | White | Intact | Positive | 12.8 | mg/cm2 |
| 25 | Rm. 03 | A | Window | Sash | Wood | White | Intact | Positive | 10.2 | mg/cm2 |
| 29 | Rm. 04 | B | Wall | | Wood | White | Intact | Positive | 4.2 | mg/cm2 |
| 37 | Rm. 04 | B | Window | Casing | Wood | Lavender | Intact | Positive | 3.4 | mg/cm2 |
| 38 | Rm. 04 | B | Window | Sash | Wood | Lavender | Intact | Positive | 3.9 | mg/cm2 |
| 41 | Rm. 05 | C | Window | Sash | Wood | Red | Intact | Positive | 6.4 | mg/cm2 |
| 42 | Rm. 05 | C | Window | Sash | Wood | Red | Intact | Positive | 4.8 | mg/cm2 |
| 45 | Rm. 06 | C | Window | Casing | Wood | Off-White | Intact | Positive | 11 | mg/cm2 |

Additionally, the exterior sides C painted wood window sashes could not be inspected due to inoperable window sashes and inaccessibility. Therefore, the **exterior sides C painted wood window sashes must be considered positive for containing lead-based paint** for the basis of this report.

A copy of this summary must be provided to new lessees (tenants) and purchasers of this property under Federal law (24 CFR part 35 and 40 CFR part 745) before they become obligated under a lease or sales contract. The complete report must also be provided to new purchasers and it must be made available to new tenants. Landlords (lessors) and sellers are also required to distribute an educational pamphlet approved by the U. S. Environmental Protection Agency and include standard warning language in their leases or sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards.

This report is submitted by Burnside Enterprises, LLC and includes a visual survey and X-Ray Fluorescence (XRF) analysis of the readily accessible painted and stained components in the surveyed area. The intent of this report is to identify if lead-based paint is present in the surveyed area, and if so, what components are affected. The presence or absence of lead-based paint or lead-based paint hazards applies only to the tested or assessed surfaces on the date of the field visit and it should be understood that conditions noted within this report were accurate at the time of the inspection and in no way reflect the conditions at the property after the date of the inspection.

Burnside Enterprises, LLC, makes no warranty, guarantee, or representation, expressed or implied, with respect to the effectiveness of any construction methods or activities regarding the containment and/or removal of lead-based paint. Our liability (Burnside Enterprises, LLC) is limited to the component surfaces that we are authorized to test using equipment, methods and procedures as set forth in the current acceptable industry guidelines, Housing and Urban Development (HUD) Guidelines Chapter 7 (revised 2012) and Colorado regulation No. 19. Burnside Enterprises, LLC assumes no responsibility for any injury to individuals or property, or for any financial loss, sustained as a result of the incorrect use or application of this report.

This report must be considered solely as a resource document representing a consensus of opinion. It is intended that this document serve as a guideline for owners or others in development of plans and activities that may be required in dealing with lead-based paint surfaces that may exist on the property. It is not the purpose or burden of this document to provide all embracing answers to every problem of lead paint. Users bear all risks associated with reliance on these results and shall have the sole responsibility to evaluate the information contained herein and to form their own independent judgments on the use of this information as may be appropriate to specific circumstances or actions.

The report also does not include evaluation of water, materials not visible (behind wall, ceiling, or floor surfaces), or adjacent property for the presence of lead hazards. Any other environmental hazards that may be found at this property are outside the scope of this report.

The paint survey report is for the exclusive private use of Colorado Springs Housing Development and Linda Clemons and the professional services of Burnside Enterprises, LLC and undertaken for and performed in the interest of Colorado Springs Housing Development and Linda Clemons. No contractual obligation is assumed for the benefit of any other person or company involved with this dwelling. Use of or reliance upon the report by other parties or for other transactions is strictly prohibited unless required by law (i.e. tenant disclosure, real estate transaction).

A copy of this summary must be provided to new lessees (tenants) and purchasers of this property under Federal law (24 CFR part 35 and 40 CFR part 745) before they become obligated under a lease or sales contract. The complete report must also be provided to new purchasers and it must be made available to new tenants. Landlords (lessors) and sellers are also required to distribute an educational pamphlet approved by the U. S. Environmental Protection Agency and include standard warning language in their

leases or sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards.

The information that follows in this report are the testing results and inspector certification that comprise the basis of this report.

A handwritten signature in cursive script that reads "John Burnside". The ink is dark and the signature is fluid.

Date: July 21, 2016

John Burnside

Burnside Enterprises, LLC - CO Inspector/Risk Assessor No. 11876

Information Page

Colorado Certified Firm

Name: Burnside Enterprises, LLC
Address: 4030 Zurich Drive, Colorado Springs, CO 80920
Phone: (719) 596-4656
Firm Certificate # 11738

Colorado Certified Lead Inspector/Risk Assessor

Name: John Burnside
Address: 4030 Zurich Drive, Colorado Springs, CO 80920
Phone: (719) 596-4656
Certificate # 11876

XRF Data

XRF Manufacturer NITON Corporation
XRF Model number XLp-300A
XRF Serial number 94979
Locations Tested See any included XRF data results
QA/QC Procedures HUD and the manufacturer's recommended calibration checks were performed

NLLAP Lab – For Laboratory Samples

Name: EMSL Analytical, Inc.
Address: 2001 East 52nd St, Indianapolis, IN 46205
Phone: 317-803-2997
Accreditation # 157245
Dust & Soil Method: EPA SW846,7420 – implementing a microwave-assisted digestion process

XRF READINGS

Note: Under the heading “Side” listed in the following data table, the listing “A” would refer to the address side wall of the dwelling with the B, C, and D designations referring to the remaining walls in a clockwise rotation.

| No | Room | Side | Structure | Feature | Substrate | Color | Condition | Results | PbC | Units |
|----|-----------|------|-----------|----------|-----------|-----------|-----------|----------|------|--------|
| 1 | Calibrate | | | | | | | Positive | 1.1 | mg/cm2 |
| 2 | Calibrate | | | | | | | Positive | 1.1 | mg/cm2 |
| 3 | Calibrate | | | | | | | Positive | 1 | mg/cm2 |
| 4 | Exterior | A | Window | Sash | Wood | Green | Poor | Positive | 1.8 | mg/cm2 |
| 5 | Exterior | A | Window | Frame | Wood | Green | Poor | Positive | 5.4 | mg/cm2 |
| 6 | Exterior | A | Door | Jamb | Wood | White | Intact | Negative | 0 | mg/cm2 |
| 7 | Exterior | A | Door | | Wood | Stained | Intact | Negative | 0 | mg/cm2 |
| 8 | Exterior | B | Window | Frame | Wood | Green | Poor | Positive | 5.2 | mg/cm2 |
| 9 | Exterior | B | Window | Sash | Wood | Green | Poor | Negative | 0.6 | mg/cm2 |
| 10 | Exterior | B | Window | Casing | Wood | White | Fair | Negative | 0.02 | mg/cm2 |
| 11 | Exterior | C | Door | Jamb | Wood | White | Intact | Negative | 0 | mg/cm2 |
| 12 | Exterior | C | Door | Screen | Wood | White | Intact | Negative | 0 | mg/cm2 |
| 13 | Exterior | C | Door | | Wood | Stained | Intact | Negative | 0 | mg/cm2 |
| 14 | Exterior | C | Window | Casing | Wood | White | Intact | Negative | 0.01 | mg/cm2 |
| 15 | Exterior | C | Door | Basement | Wood | Brown | Poor | Negative | 0 | mg/cm2 |
| 16 | Exterior | D | Window | Sash | Wood | Green | Poor | Positive | 1.4 | mg/cm2 |
| 17 | Exterior | D | Window | Casing | Wood | Red | Intact | Negative | 0.01 | mg/cm2 |
| 18 | Rm. 01 | A | Window | Casing | Wood | Brown | Intact | Positive | 11.7 | mg/cm2 |
| 19 | Rm. 01 | A | Window | Sash | Wood | Brown | Intact | Positive | 9.3 | mg/cm2 |
| 20 | Rm. 02 | A | Window | Casing | Wood | Off-White | Intact | Positive | 7 | mg/cm2 |
| 21 | Rm. 02 | A | Window | Sash | Wood | Off-White | Intact | Positive | 5.4 | mg/cm2 |
| 22 | Rm. 02 | A | Door | Casing | Wood | Off-White | Intact | Negative | 0 | mg/cm2 |
| 23 | Rm. 02 | A | Door | | Wood | Stained | Intact | Negative | 0 | mg/cm2 |
| 24 | Rm. 03 | A | Window | Casing | Wood | White | Intact | Positive | 12.8 | mg/cm2 |
| 25 | Rm. 03 | A | Window | Sash | Wood | White | Intact | Positive | 10.2 | mg/cm2 |
| 26 | Rm. 04 | A | Ceiling | | Plaster | White | Intact | Negative | 0 | mg/cm2 |
| 27 | Rm. 04 | A | Wall | | Plaster | White | Intact | Negative | 0 | mg/cm2 |
| 28 | Rm. 04 | A | Wall | | Wood | White | Intact | Negative | 0 | mg/cm2 |
| 29 | Rm. 04 | B | Wall | | Wood | White | Intact | Positive | 4.2 | mg/cm2 |
| 30 | Rm. 04 | B | Wall | | Plaster | White | Intact | Negative | 0.07 | mg/cm2 |
| 31 | Rm. 04 | C | Wall | | Plaster | White | Intact | Negative | 0 | mg/cm2 |
| 32 | Rm. 04 | D | Wall | | Plaster | White | Intact | Negative | 0 | mg/cm2 |

| No | Room | Side | Structure | Feature | Substrate | Color | Condition | Results | PbC | Units |
|----|-----------|------|-----------|------------|-----------|-----------|-----------|----------|-----|--------|
| 33 | Rm. 04 | D | Wall | Crown Mldg | Wood | Lavender | Intact | Negative | 0 | mg/cm2 |
| 34 | Rm. 04 | D | Door | Casing | Wood | Lavender | Intact | Negative | 0 | mg/cm2 |
| 35 | Rm. 04 | D | Door | Jamb | Wood | White | Intact | Negative | 0 | mg/cm2 |
| 36 | Rm. 04 | D | Door | | Wood | White | Intact | Negative | 0 | mg/cm2 |
| 37 | Rm. 04 | B | Window | Casing | Wood | Lavender | Intact | Positive | 3.4 | mg/cm2 |
| 38 | Rm. 04 | B | Window | Sash | Wood | Lavender | Intact | Positive | 3.9 | mg/cm2 |
| 39 | Rm. 04 | D | Cabinet | Door | Wood | Stained | Intact | Negative | 0 | mg/cm2 |
| 40 | Rm. 04 | D | Cabinet | Frame | Wood | Stained | Intact | Negative | 0 | mg/cm2 |
| 41 | Rm. 05 | C | Window | Sash | Wood | Red | Intact | Positive | 6.4 | mg/cm2 |
| 42 | Rm. 05 | C | Window | Sash | Wood | Red | Intact | Positive | 4.8 | mg/cm2 |
| 43 | Rm. 05 | C | Door | Casing | Wood | Red | Intact | Negative | 0 | mg/cm2 |
| 44 | Rm. 05 | C | Door | | Wood | Stained | Intact | Negative | 0 | mg/cm2 |
| 45 | Rm. 06 | C | Window | Casing | Wood | Off-White | Intact | Positive | 11 | mg/cm2 |
| 46 | Rm. 06 | C | Window | Sash | Wood | Off-White | Intact | Negative | 0 | mg/cm2 |
| 47 | Calibrate | | | | | | | Positive | 1.1 | mg/cm2 |
| 48 | Calibrate | | | | | | | Positive | 1.1 | mg/cm2 |
| 49 | Calibrate | | | | | | | Positive | 1.1 | mg/cm2 |



22 W Mill St, Colo Spgs
Not To Scale